

0032054748444660

FIG. 1




FIG. 3





FIG. 2






FIG. 4




FIG. 5




FIG. 6




FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D




FIG. 7E




FIG. 7F




FIG. 7G




FIG. 7H




FIG. 7I




FIG. 7J




FIG. 7K





FIG. 7L

1960050 61284860

FIG. 8



0 6384461 - 05 02 00





FIG. 9

FIG. 10A



00000000000000000000000000000000

CIRCUMFERENCE OF  
STENT




FIG. 10B

106